





USER MANUAL



1. Mount foot and pole.



1.2 Place base [P1] flat. Align Pole [P2], Secure from underneath with 4x Base Screws [A] using Allen key [C]

1.1


2. Mount head



2.2 Secure with Screw [B] using Allen Key [D]






2.3 Tilt Head



3.1 Insert Power cable thru base [P1] and Pole [P2]

3. Insert power cable

4. Insert Tab



3.2 Insert Power cable thru Head [P3]

4.1 Insert Tab into Jaws of Head [P3]

4.2 After Inserting Tab Tight Jaws and fix it with 4x screws on back side of Head [P3] with Allen key [E]

4.3 Insert Power Cable and turn on Tab

PROPRIETARY AND CONFIDENTIAL

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF SN SYSTEMS. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF SN SYSTEMS IS PROHIBITED.

